


Lift-Rite (Big Joe) L-50 Hydraulic Unit







Lift-Rite (Big Joe) L-50 Hydraulic Unit

Iten	n	Part No.	Description I	ist Price	Item	Part No.	Description	List Price
1		10236-B-A-HD	Steer Wheel Assy, Red Ultra Poly On	\$55.00	37	10269	Roll Pin	\$0.50
			Alum. Hub W/Bearings, 25mm Bea	ring ID	38	10268	Release Lever	\$18.00
		10236-B-A-ST	Steer Wheel Assembly, Poly On Nylo	n \$38.00	39	10242	Roll Pin	\$0.50
			Hub W/ Bearings, 25mm Bearing II)	40	10234	Thrust Bearing	\$12.00
		10236-B-N-A	Steer Wheel Assembly, Nylon	\$36.00		10234-HD	Heavy DutyThrust Bearing (Newer S	Style)\$32.00
			W/ Bearings, 25mm Bearing ID		41	10235	Snap Ring	\$1.00
		10236-B-S-A	Steer Wheel Assembly, Steel	\$59.00	42	10239	Washer	\$1.00
			W/ Bearings, 25mm Bearing ID		43	10236-R-A-HD	Steer Wheel Assy, Red Ultra Poly O	n \$55.00
		GWK-L50-CK	Comp. Wheel Kit, Incl (2) LR Assy,	\$124.95			Alum. Hub W/Bearings, 1" Bearin	g ID
			(2) SW Assy W/ Bearings, Axles, Fas	steners		10236-R-A-ST	Steer Wheel Assembly, Black Poly	On \$38.00
2		10237	Snap Ring	\$0.50			Nylon Hub W/ Bearings, 1" Bearing	g ID
3		10238-B	Ball Bearing (OEM Wheel Only)	\$5.00		10236-R-N-A	Steer Wheel Assembly, Nylon	\$36.00
4		10239	Washer	\$1.00			W/ Bearings, 1" Bearing ID	
5		10240-E	Steer Wheel Axle, 25mm OD	\$12.00	44	10240	Steer Wheel Axle, 8" Length, 1" 0	D \$12.00
6		10236-C	Hub Cap	\$7.50			(for Roller Bearing)	,
7		10250	Pump Piston Assembly	\$24.00	45 A E	B C 10261	Ball	\$2.00
8		10253	Spring	\$12.00		B C 10261-A	Ball	\$1.00
9	ΑВ	10251	Scraper	\$5.00	46	10276-A	Handle Assembly	\$99.00
10	AB	10252	U-Cup	\$12.00	47	10238-A	Flanged Bearing	\$5.00
11	7,5	10277-B	Sleeve	\$5.00		10238-R	Roller Bearing (For OEM Wheel On	
12		10277-A	Roll Pin	\$0.50	48 A I		0-Ring	\$1.00
13	ΛRC	2 10261	Ball	\$2.00	49 A		Release Pin	\$12.00
14	AC		Valve	\$12.00	50	10257	Nut	\$5.00
15	AC	10263	Roll Pin	\$0.50	51	10257 10257-B	Screw	\$1.00
16	AC	10266	Screw Plug	\$5.00	52 A		Washer	\$3.00
17	AB	10265	0-Ring	\$1.00	53 A		Spring	\$5.00
18	AC	10265		\$1.00		B C 10254	Ball	\$1.50
19	AU	10204 10274-E	Spring	\$3.00		C 10254		\$2.00
	A D		Handle Cap				Spring	\$2.00
20	A B	10256	0-Ring	\$3.00	56 A I		Washer	
21		10274-B	Control Lever	\$18.00	57	10267	Filler Plug	\$1.00
22		10274-D	Roll Pin	\$0.50	58 A I		U-Cup	\$12.00
23		10274-A	Control Rod	\$17.00	59 A I		U-Cup	\$17.00
24		10273	Pin	\$1.50	60 A I		Scraper	\$5.00
25		10272	Chain	\$7.00	61	10243	Ram	*49.00
26		10206	Bushing	\$2.00	62	10244	Ball	\$2.50
27		10270	Lower Control Rod	\$10.00	64	10274-F	Bolt	\$1.00
28		10271	Adjusting Nut	\$0.50	65	10274-G	Lock Washer	\$0.50
29		10274-S	Roll Pin	\$0.50	66	10241	Washer	\$2.00
30		10274-R	Roller	\$10.00	67	10234-A	Washer	\$5.00
31		10275	Shoulder Bolt (Hex Head)	\$6.50	KITS A	10278-SUPER	Super Seal Kit	\$49.00
		10275-A	Shoulder Bolt (Allen Head)	\$6.00	KITS B	10278	Seal Kit	\$39.00
32		10203	Bushing	\$2.00	KITS C	10279	Seal Kit (Ball and Valve Kit)	\$19.00
		10203-A	Bushing	\$2.00		HU LF L50	Rebuilt Hydraulic Unit - Exchange	*139.00
34		10274-P	Pin	\$6.00		B40217	Brake Cable Assembly	\$40.00
35		10274-C	Spring	\$3.00		B40220	Brake Wheel	*80.00
36		10233	Spacer Prices subject to change without noti	\$8.00 ce. All manufactu	urers' names, p	part numbers and descri	*Non-discounting it ptions are used for reference purposes or	